FeatureCAM 2023 cheat sheet

General

Alt + [1 - 9]	Quick access toolbar items
Alt + Right arrow	Step simulation forward one step
Alt + Left arrow	Step simulation backward one step
Alt + Enter	Properties
Alt + F1	Centerline simulation
Alt + F2	Play/pause simulation
Alt + F3	Single-step simulation
Alt + L	Last view
Alt + R	Refresh
Alt + Shift + V	Save view
Ctrl + Left click	(click a column of any list box that does sorting) Activate the second level of sorting
Ctrl + Left click	(click a viewing mode button) Stay in that viewing mode
Ctrl + Left click	Run 3D simulation in hidden line mode and do continuous looping
Ctrl + Left click	the Play button when Home tab > Simulation panel > Sim Mode > Machine is selected. (click the Play button when Home tab > Simulation panel > Sim Mode > 3D is selected) Run machine simulation in hidden line mode and do continuous looping
Ctrl + 0	Bottom view
Ctrl + 1	Isometric view
Ctrl + 2	Front view
Ctrl + 3	Isometric 2 view
Ctrl + 4	Left view
Ctrl + 5	Top view
Ctrl + 6	Right view
Ctrl + 7	Isometric 4 view
Ctrl + 8	Back view
Ctrl + 9	Isometric 3 view
Ctrl + A	Select all
Ctrl + C	Copy
Ctrl + E	Center selected
Ctrl + F	Find (text in a text window). The cursor must be in a text window

Ctrl + H	Replace (text in a text window). The cursor must be in a text window
Ctrl + J	Hide selected
Ctrl + K	Hide unselected
Ctrl + L	Center all
Ctrl + N	New file
Ctrl + O	Open file
Ctrl + P	Print
Ctrl + R	Display the New Feature wizard
Ctrl + S	Save file
Ctrl + V	Paste
Ctrl + X	Cut
Ctrl + Y	Redo
Ctrl + Z	Undo
Ctrl + Left click	(click the Pick Curve button) Causes the warp status for that dialog to toggle
Ctrl + Left click	(click the Pick Curve button while a feature is selected) Toggles between simulation of the selection feature and the entire Setup
Ctrl + Left click	(click the Play button) Run simulation in hidden line mode
Ctrl	(hold Ctrl while toolpath is being computed) Temporarily turns off Toolpath Computation Minimization. Toolpaths are recomputed for all features even if that feature did not change
Ctrl + Shift + Left click	(click the Play button when Home tab > Simulation panel > Sim Mode > 3D is selected) Continuous loop simulation for 3D simulation
Ctrl + Shift + Left click	(click the Play button when Home tab > Simulation panel > Sim Mode > Machine is selected) Continuous loop simulation for machine simulation
Ctrl + Shift + A	Shade selected
Ctrl + Shift + C	Unshade all
Ctrl + Shift + N	Unshade selected

Ctrl + Shift + P	Toggle perspective
Del	Delete the selected object
Esc	Stop current simulation
F1	Context-sensitive help
Middle click + Move the mouse	(drag in the graphics window) Performs viewing based on the current viewing mode

The mouse wheel-click-and-drag also performs this function.

Wheel up and wheel down	Zoom
Shift + Left click	(click an edge when filleting) Selects all edges of the face and adds them to the list
Shift + Left click	(click the NC Code tab) Show ACL instead of NC code
Shift + Left click	(click while clipping when Multiple Region is On) Removes the entire picked region instead of to the nearest intersection.
Shift + Right click	(right click in graphics window) Dynamic viewing using current view mode.
Shift + Left click	(click the Show button in the SCL dialog) Displays a dialog that shows the attributes of the model selected in SCL dialog.

Source: Autodesk support

Last modification: 6/10/2022 10:48:54 AM

More information: *defkey.com/autodesk-featurecam-2023-shortcuts*

Customize this PDF...