

# F Fusion 360 cheat sheet

## Animate Workspace Commands

U	Auto Explode All Levels
E	Manual Explode
P	Publish Video
M	Transform Components
C	View

## CAM Workspace Commands

Ctrl + D or Cmd + D	Duplicate
Ctrl + G or Cmd + G	Generate Toolpath
Shift + S	Scripts and Add-Ins
Ctrl + L or Cmd + L	Show Log

## Canvas Selection

Ctrl + C or Cmd + C	Copy
Ctrl + X or Cmd + X	Cut
Shift + Middle click	(hold Shift and the middle mouse button) Orbit
Shift + Left click then Middle click	(hold Shift + click then hold middle mouse button) Orbit around point
Middle click	(hold) Pan
Ctrl + V or Cmd + V	Paste
Ctrl + Y or Cmd + Y	Redo
Ctrl + Z or Cmd + Z	Undo
Wheel up and wheel down	Zoom

## Drawing Workspace Commands

B	Balloon
C	Center Mark
Del	Delete
D	Dimension

M	Move
P	Projected View
T	Text

## Edit Form Commands

Alt + Left click + Move the mouse	Add geometry
Alt + Ctrl + Left click + Move the mouse or Alt + Cmd + Left click + Move the mouse	Add geometry and keep creases

## Electronics workspace

/	Activate command line
H	Add Hole
A	Add Part
T	Add Text
B	Bus
C	Change
Ctrl + C or Cmd + C	Copy
Del or Backspace	Delete
D	Dimension
Ctrl + or Cmd + D	DRC
Ctrl + E or Cmd + E	ERC
E	Errors
G	Grid
Shift + L	Label
R	Manual Route
R	Move
N	Name
R	Net
Alt + Ctrl + 3 or Option + Cmd + 3	New Device
Alt + Ctrl + 2 or Option + Cmd + 2	New Footprint
Alt + Ctrl + 1 or Option + Cmd + 1	New Symbol
Alt + Ctrl + 4 or Option + Cmd + 4	Package 3D Create

O	Pad
Shift + O	Pad Array
P	Pin
Shift + P	Pin Array
Ctrl + Y or Cmd + Shift + Z	Redo
U	Ripup
Alt + Shift + P or Option + Shift + P	Ripup All Polygons
Ctrl + R or Cmd + R	Route Diff Pair
Shift + R	Route Multi
Alt + Shift + S or Option + Shift + S	Run Script
Shift + U	Run ULP
P	SMD
Shift + P	SMD Array
Esc	Stop
Ctrl + Z or Cmd + Z	Undo
V	Value
Alt + V or Option + V	Via
F6	Zoom to Fit
Ctrl + 1 or Cmd + 1	Switch Sch Doc
Ctrl + 2 or Cmd + 2	Switch PCB Doc
Ctrl + 3 or Cmd + 3	PCB 3D View
S	Shortcut Dialog

## Generative Design workspace

N	New Generative Study
E	Study Settings
C	Structural Constraints
L	Structural Loads

## Modeling Commands

R	2-point Rectangle
A	Appearance

Shift + J	As-built Joint
C	Center Diameter Circle
Ctrl + B or Cmd + B	Compute All
E	Extrude
F	Fillet
2	Freeform Selection
H	Hole
J	Joint
L	Line
I	Measure
S	Model Toolbox
M	Move
X	Normal / Construction
O	Offset
3	Paint Selection
Q	Press Pull
P	Project
Shift + S	Scripts and Add-Ins
D	Sketch Dimension
Shift + N	Toggle Component Color Cycling
V	Toggle Visibility
T	Trim
1	Window Selection

## Render Workspace Commands

A	Appearance
---	------------

## Sculpt Workspace Selection

Shift + Up arrow	Grow selection
Alt + N or Cmd + N	Invert selection
Alt + O or Control + O	Loop grow selection
Alt + P or Control + P	Loop selection
Alt + Right arrow or Control + Cmd + Right arrow	Next U
Alt + Up arrow or	Next V

Control + Cmd +  
Up arrow

Alt + Left arrow or Control + Cmd + Left arrow	Previous U
--	------------

Alt + Down arrow or Control + Cmd + Down arrow	Previous V
--	------------

Alt + M or Cmd + M	Range selection
-----------------------	-----------------

Alt + K or Control + K	Ring grow selection
---------------------------	---------------------

Alt + L or Control + L	Ring selection
---------------------------	----------------

Alt + J or Control + J	Ring shrink selection
---------------------------	-----------------------

Double click	(double-click an edge) Select edge ring
--------------	---

Double click	Select two faces then double-click a third face: Select face ring
--------------	---

Shift + Down arrow	Shrink selection
-----------------------	------------------

Ctrl + 1 or Control + 1	Toggle box mode
----------------------------	-----------------

Ctrl + 2 or Control + 2	Toggle control frame mode
----------------------------	---------------------------

Ctrl + 3 or Control + 3	Toggle smooth mode
----------------------------	--------------------

## Simulate Workspace Selection

Ctrl + D or Cmd + D	DOF View
------------------------	----------

F	Force
---	-------

Ctrl + G or Cmd + G	Groups View
------------------------	-------------

Ctrl + L or Cmd + L	Model View
------------------------	------------

N	New Simulation Study
---	----------------------

Ctrl + R or Cmd + R	Results View
------------------------	--------------

E	Settings
---	----------

C	Structural Constraint
---	-----------------------

L	Structural Loads
---	------------------

## System

Ctrl + Shift + S or Cmd + Shift + S	Recovery Save
--	---------------

Ctrl + S or Cmd + S	Save Version
------------------------	--------------

Source: Autodesk

Last modification: 22/4/1442 هـ 7:44:17 ص

More information: [defkey.com/ar/autodesk-fusion-360-shortcuts](https://defkey.com/ar/autodesk-fusion-360-shortcuts)

[Customize this PDF...](#)