

Dx Dialux Evo cheat sheet

General

F1	Help
F2	Coordinates system on/off
F3	Help lines on/off
F4	User planes/areas on/off
F5	Wire mesh view on/off
F6	Isolines on/off
F7	DWG on/off
F8	Light distribution curve on/off
F9	Global false colours on/off
F10	Selection menu bar
F11	Report translation error
F12	Save as
Ctrl + X	Cut
Ctrl + C	Copy
Ctrl + V	Insert
Alt + Right click	Set focal width of camera
Ctrl + M	Insert at mouse/cursor position
Ctrl + N	New project
Ctrl + O	Open
Ctrl + S	Save
Ctrl + P	Print
Ctrl + Z	Undo
Ctrl + Y	Redo
Del	Delete
Shift	Cancel toggle
Ctrl + +	CAD-zoom +
Ctrl + -	CAD-zoom -
Ctrl + *	CAD-zoom reset
Shift + +	GUI-zoom +
Shift + -	GUI-zoom -
Shift + *	GUI-zoom reset
Esc	Cancel selection
Esc	Exit
Ctrl + 1	Save position 1
Ctrl + 2	Save position 2
Ctrl + 3	Save position 3
Ctrl + 4	Save position 4
Ctrl + 5	Save position 5

Ctrl + 6	Save position 6
Ctrl + 7	Save position 7
Ctrl + 8	Save position 8
Ctrl + 9	Save position 9
Ctrl + 0	Save position 10
Alt + 1	Restore position 1
Alt + 2	Restore position 2
Alt + 3	Restore position 3
Alt + 4	Restore position 4
Alt + 5	Restore position 5
Alt + 6	Restore position 6
Alt + 7	Restore position 7
Alt + 8	Restore position 8
Alt + 9	Restore position 9
Alt + 0	Restore position 10

Control with a touchpad

Z + Left click	Zoom
P + Left click	CAD Pan
W/A/S/D	Move in the CAD

Source: dial.de

Last modification: 24/2/2023 9:42:26

More information: defkey.com/es/dialux-evo-shortcuts

[Customize this PDF...](#)