



EasyEDA cheat sheet

Entire document

| | |
|-----------------|--|
| Space | Rotate selected objects |
| Right click | Keep right-click to pan canvas; Open offset dialog when select one object |
| Left arrow | Scroll Or Move selected left |
| Right arrow | Scroll or Move selected right |
| Up arrow | Scroll or Move selected up |
| Down arrow | Scroll or Move selected down |
| Tab | Change object's attributes when placing; Open offset dialog when selecting an object |
| Esc | Cancel current drawing |
| Home | Set new canvas origin |
| Del | Delete Selected |
| F1 | Open tutorials |
| F11 | Full screen at browser |
| A | Zoom In |
| Z | Zoom Out |
| D | Drag |
| K | Fit Window |
| R | Rotate selected objects |
| X | Flip Horizontal (doesn't support footprint) |
| Y | Flip Vertical (doesn't support footprint) |
| Alt + F5 | Full screen at browser |
| Alt + W | Close current tab |
| Shift + Alt + W | Close all tabs |
| Ctrl + X | Cut |
| Ctrl + C | Copy |
| Ctrl + V | Paste |
| Ctrl + A | Select All |
| Ctrl + Z | Undo |
| Ctrl + Y | Redo |
| Ctrl + S | Save |
| Ctrl + F | Find Component |
| Ctrl + D | Design Manager |
| Ctrl + Home | Open canvas origin setting dialog |

| | |
|-------------------------------------|---|
| Shift + 1 | Cycle forward to next open tabbed document |
| Shift + 2 | Cycle backward to next open tabbed document |
| Shift + X | Cross Probe |
| Shift + F | Search Library |
| Shift + Left click + Move the mouse | Cursor snap to part's origin |
| E | Align horizontal centers |
| Shift + Alt + E | Align vertical centers |
| Ctrl + Shift + L | Align left |
| Ctrl + Shift + R | Align right |
| Ctrl + Shift + O | Align top |
| Ctrl + Shift + B | Align bottom |
| Ctrl + Shift + G | Align grid |
| Ctrl + Shift + H | Distribute Horizontally |
| Ctrl + Shift + E | Distribute Vertically |
| Ctrl + Shift + F | Find similar objects |

Schematic

| | |
|------------------|-----------------------------|
| W | Draw Wire |
| B | Draw Bus |
| U | Bus Entry |
| N | NetLabel |
| P | Place Pin |
| L | Draw Polyline |
| O | Draw Polygon |
| Q | Draw Bezier |
| C | Draw Arc |
| S | Draw Rect |
| E | Draw Ellipse |
| F | Freehand Draw |
| T | Place Text |
| I | Edit Selected Symbol |
| Ctrl + Q | NetFlag VCC |
| Ctrl + G | NetFlag GND |
| F8 | Run the Document Simulation |
| Ctrl + J | Open the Simulation Setting |
| Ctrl + Shift + X | Cross Probe and Place |
| Shift + T | Open symbol wizard |

| | |
|---------------------------|---|
| Alt + F | Open footprint manager |
| PCB | |
| W | Draw Track |
| U | Draw Arc |
| C | Draw Circle |
| N | Draw Dimension |
| S | Draw Text |
| O | Draw Connect |
| E | Draw copperArea |
| T | Change To TopLayer; Change selected part to toplayer |
| B | Change To BottomLayer; Change selected part to bottomlayer |
| 1 | Change To Inner1 |
| 2 | Change To Inner2 |
| 3 | Change To Inner3 |
| 4 | Change To Inner4 |
| P | Place Pad |
| Q | Change canvas unit |
| V | Place Via |
| M | Measure |
| H | Highlight Net all the time, press it again cancel highlight |
| L or Ctrl + Shift + Space | Change Route Angle |
| - | Decrease Routing Width; Switch to the forward signal layer |
| + | Increase Routing Width; Switch to the next signal layer |
| * | Cycle switch to the next signal layer |
| Del | Delete selected object; Undo the track when routing |
| Alt + - | Decrease Snap Size |
| Alt + + | Increase Snap Size |
| Ctrl + R | Depend on reference point for copy object repeatedly |
| Ctrl + L | Open layer manager |
| Ctrl + Q | Hide/show network text |
| Shift + M | Remove All Copper Area fill data |

| | |
|------------------------|---|
| Shift + B | Rebuild All Copper Area |
| Shift + D | Move Object(s) by reference point |
| Shift + G | Display track length while routing |
| Shift + W | Show favorite track width while routing |
| Shift + R | Change routing conflict |
| Shift + S | Toggle layers which is not active |
| Shift + Double click | Delete selected track segment |
| Ctrl + Shift + V | Paste object(s) and keep the prefix, and hide the ratline layer |
| Ctrl + Alt + L | Enable all layers |
| Ctrl + Shift + Alt + D | Open custom data dialog |

Source: EasyEDA docs

Last modification: 1/4/2022 15:33:47

More information: defkey.com/ha/easyeda-shortcuts

[Customize this PDF...](#)