



Creo View 8 cheat sheet

General

Ctrl + Shift + Del	Clear annotations
Ctrl + Del	Clear measurements
Ctrl + F4	Close window
F1	Context help
Del	Delete
Esc	Exit current mode (return to select mode)
Ctrl + F	Find
F5	Primary panel (toggle on/off)
F6	Upper data panel (toggle on/off)
F7	Lower data panel (toggle on/off)
Ctrl + F8	Only display view window
Ctrl + P	Print
Ctrl + F3	Free rotation mode
S	Smart selection filter
M	Markup selection filter
Ctrl + A	Select all
Ctrl + Shift + I	Invert selection
F3	Transform mode
Ctrl + Shift + A	Zoom all
Ctrl + + + -	Zoom out
Ctrl + + + +	Zoom in
Ctrl + Shift + S	Zoom selected
Ctrl + Shift + Z	Zoom window
R or L	Rotate
T	Rotate (top)
B	Rotate (bottom)
N	Rotate (front)
K	Rotate (back)
Home	First page
End	Last page
Page Up	Previous page
Page Down	Next page

MCAD

F9	Render shaded
F10	Render shaded with edges
F11	Render hidden line removal

F12	Render wireframe
Ctrl + .	Spin center
Space	Start or stop animation playback
P	Part selection filter
C	Construction geometry selection filter
A	Model annotations selection filter
F	Faces selection filter
E	Edges selection filter
O	Points selection filter
X	Axes selection filter
Ctrl + I	Isolate selected
Ctrl + H	Hide selected
Ctrl + U	Unhide all
Shift + +	Switch from origin mode to center mode after using transform mode

ECAD

F	Fill shape
U	Flip board
X	Crosshair
Shift + .	Center on selected
Ctrl + Home	Zoom to outline
E	Pinpads selection filter
X	Via pads selection filter

Source: PTC Support

Last modification: 2022. 02. 15. 15:28:19

More information: defkey.com/hu/creo-view-8-shortcuts

[Customize this PDF...](#)