Navisworks Freedom 2020 cheat sheet

General

Page Up	Zooms to view all objects in the Scene View.
Page Down	Zooms to magnify all selected objects in the Scene View.
Home	Takes you to Home view. This keyboard shortcut only applies to the Scene View windows. This means it will only work when this window has focus.
Esc	Deselects everything.
Shift or Ctrl	Used to modify the middle mouse button actions.
Alt	Turns the keytips on or off.
Alt + F4	Closes the currently active dockable window when it is undocked, or exits the application if the main application window is active.
Ctrl + 0	Turns on Turntable mode.
Ctrl + 1	Turns on Select mode.
Ctrl + 2	Turns on Walk mode.
Ctrl + 3	Turns on Look Around mode.
Ctrl + 4	Turns on Zoom mode.
Ctrl + 5	Turns on Zoom Window mode.
Ctrl + 6	Turns on Pan mode.
Ctrl + 7	Turns on Orbit mode.
Ctrl + 8	Turns on Free Orbit mode.
Ctrl + 9	Turns on Fly mode.
Ctrl + A	Displays the Append dialog box.
Ctrl + D	Toggles Collision mode. You must be in appropriate navigation mode (that is, Walk or Fly) for this keyboard shortcut to work.
Ctrl + F	Displays the Quick Find dialog box.
Ctrl + G	Toggles Gravity mode.
Ctrl + H	Toggles Hidden mode for selected items.
Ctrl + I	Displays the Insert From File dialog box.
Ctrl + M	Displays the Merge dialog box.

Ctrl + N	Resets the program, closes the currently open Autodesk Navisworks file, and creates a new file.
Ctrl + O	Displays the Open dialog box.
Ctrl + P	Displays the Print dialog box.
Ctrl + R	Toggles Require mode for selected items.
Ctrl + S	Saves the currently open Autodesk Navisworks file.
Ctrl + T	Toggles Third Person mode.
Ctrl + Y	Reverses the last operation performed by the Undo command.
Ctrl + Z	Reverses the last performed operation.
Ctrl + Page Up	Displays the previous sheet.
Ctrl + Page Down	Displays the next sheet.
Ctrl + F1	Opens the Help system.
Ctrl + F2	Opens the Clash Detective window. This feature is available for Autodesk Navisworks Manage users only.
Ctrl + F3	Toggles the TimeLiner window.
Ctrl + F3	Toggles the TimeLiner Playback window.
Ctrl + F4	Toggles the docking window for the currently active graphics system (i.e. the Autodesk Rendering window).
Ctrl + F5	Toggles the Animator window.
Ctrl + F6	Toggles the Scripter window.
Ctrl + F7	Toggles the Tilt window.
Ctrl + F8	Toggles the Quantification Workbook window.
Ctrl + F9	Toggles the Plan View window.
Ctrl + F10	Toggles the Section View window.
Ctrl + F11	Toggles the Saved Viewpoints window.
Ctrl + F12	Toggles the Selection Tree window.
Ctrl + Home	Dollies and pans the camera so that the entire model is in view.

Ctrl + Right arrow	Play selected animation.
Ctrl + Left arrow	Reverse Play selected animation.
Ctrl + Up arrow	Record viewpoint animation.
Ctrl + Down arrow	Stop playing animation.
Ctrl + Space	Pause playing animation.
Ctrl + Shift + A	Opens the Animation Export dialog box.
Ctrl + Shift + C	Opens the Export dialog box and enables you to export current search.
Ctrl + Shift + I	Opens the Image Export dialog box.
Ctrl + Shift + R	Opens the Export Rendered Image dialog box.
Ctrl + Shift + S	Opens the Export dialog box and enables you to export search sets.
Ctrl + Shift + T	Opens the Export dialog box and enables you to export the current TimeLiner schedule.
Ctrl + Shift + V	Opens the Export dialog box and enables you to export viewpoints.
Ctrl + Shift + W	Opens the Export dialog box and enables you to export viewpoint report.
Ctrl + Shift + Home	Sets current view as Home.
Ctrl + Shift + End	Sets current view as Front.
Ctrl + Shift + Left arrow	Arrow Takes you to the previous redline tag.
Ctrl + Shift + Right arrow	Arrow Takes you to the next redline tag.
Ctrl + Shift + Up arrow	Takes you to the first redline tag.
Ctrl + Shift + Down arrow	Takes you to the last redline tag.
F1	Opens the Help system.
F2	Renames the selected item, when appropriate.
F3	Repeats the previously run Quick Find search.
F5	Refreshes your scene with the

	latest versions of currently loaded model files.
F11	Toggles Full Screen mode.
F12	Opens the Options Editor.
Shift + W	Opens the last used SteeringWheel.
Shift + F1	Enables you to get context- sensitive help.
Shift + F2	Toggles the Sets window.
Shift + F3	Toggles the Find Items window.
Shift + F4	Toggles the Find Comments window.
Shift + F6	Toggles the Comments window.
Shift + F7	Toggles the Properties window.
Shift + F10	Opens a context menu.
Shift + F11	Opens the File Options dialog box.

TimeLiner Tasks and Simulate tabs

Esc	Cancels the current edits.
F2 or Letter	Starts editing the selected field.
Right arrow	ARROW Moves the selection to the next right field, unless the current field is in a tree column that can be expanded. In this case, it expands the row.
Left arrow	ARROW Moves the selection to the next left field, unless the current field is in a tree column that can be expanded. In this case, it expands the row.
Up arrow / Down arrow	Selects the row above/below the current row
Shift + Up arrow / Down arrow	Extends the selection to the row above/below the current row.
Ctrl + Up arrow / Down arrow	Moves the current row up/down without changing selection.
Home	Selects the first row.
Shift + Home	Extends the selection from the selection anchor to the first row.
Ctrl + Home	Moves the current row to the first row without changing selection.
Ctrl + Shift + Home	Adds the rows from the current row to the first row to the

	selection.
End	Selects the last row.
Shift + End	Extends the selection from the selection anchor to the end.
Ctrl + End	Moves the current row to the last row without changing selection.
Ctrl + Shift + End	Adds the rows from the current row to the last row to the selection.
Page Up / Down	Selects the row one page above/below the current row.
Shift + Page Up / Down	Extends the selection one page up/down.
Ctrl + Page Up / Down	Moves the current row one page up/down without changing the selection.
Ctrl + Shift + Page Up / Down	Adds one page up/down from the current row to the selection.
*	Expands the entire subtree, starting from the current cell. Can also be used to expand Viewpoints.

Measure Tools panel, the Lock

feature

Х	Lock to the X axis
Υ	Lock to the Y axis
Z	Lock to the Z axis
Ρ	Lock to a point perpendicular to a surface
L	Lock to a point parallel to a surface
Enter	Quick zoom to measured area
+	Use with Enter key to zoom in to measured area
-	Use with Enter key to zoom out of measured area

Source: Autodesk

Last modification: 17.11.2019 20:44:35

More information: defkey.com/ru/autodesknavisworks-freedom-2020-shortcuts

Customize this PDF...