



Tekla Structures 20 cheat sheet

Representation for parts

Ctrl + 1	Wire frame
Ctrl + 2	Shaded wire frame
Ctrl + 3	Hidden lines
Ctrl + 4	Rendered
Ctrl + 5	Show only selected

Representation for component parts

Shift + 1	Wire frame
Shift + 2	Shaded wire frame
Shift + 3	Hidden lines
Shift + 4	Rendered
Shift + 5	Show only selected

General

F1	Help
Ctrl + S	Save
Alt + Enter	Properties
Ctrl + Z	Undo
Ctrl + Y	Redo
Esc	Interrupt
Enter	Repeat last command
Ctrl + K	Show / hide mini toolbar
Ctrl + I	Open Views list
Ctrl + Tab	Switch between open views
Ctrl + C	Copy
Ctrl + M	Move
Del	Delete
Ctrl + U	Update
D	Drag and drop
P	Pan
Shift + M	Middle button pan
Arrow keys	Move
Insert	Center by cursor
Home	Zoom original
Page Up	Zoom in
Page Down	Zoom out
End	Zoom previous
Z + Left click	(click row) Zoom to selected

objects

F + Left click	(click row) Fit work area to selected objects (satıra tıklayın)
Ctrl + R	Rotate with mouse
Ctrl + Arrow keys or Shift + Arrow keys	Rotate with keyboard
O	Ortho
@ or R	Relative coordinate input
\$ or A	Absolute coordinate input
Tab	Next position
Shift + Tab	Previous position
S	Smart select
Ctrl + G	Selection filter
Shift	Add to selection
Ctrl	Toggle selection
X	Lock X coordinate
Y	Lock Y coordinate
Z	Lock Z coordinate
F2	Select all selection switch
F3	Select parts selection switch
F4	Snap to reference lines / points
F5	Snap to geometry lines / points
F6	Snap to nearest points
F7	Snap to any position
Ctrl + E	Advanced options
Shift + I	Inquire object

Modeling

Ctrl + D	Switch direct modification on / off
Ctrl + N	Create new model
Ctrl + O	Open model
Shift + X	Create clip plane
H	Rollover highlight
V	Set view rotation point
F	Measure distance
Shift + R or Shift + T	Autorotate
F8	Disable view rotation
Ctrl + P	3D / Plane

Shift + F	Fly (in perspective views)
Ctrl + A	Select all
Alt + Left click	(then click object) Select assembly
Shift + H	Hide object
Backspace	Undo last polygon pick
Space	Finish polygon input
Ctrl + F	Open component catalog
Ctrl + J	Create AutoConnection
Ctrl + H	Phase manager
Ctrl + L	Open drawing list
Shift + P	Print drawings
Ctrl + B	Create report

Last modification: 4/3/2021 11:39:43 AM

More information: defkey.com/ur/tekla-structures-20-shortcuts

[Customize this PDF...](#)

Drawing

Shift + A	Associative symbol
Ctrl + O	Open drawing list
B	Set next drawing color mode
Shift + G	Ghost outline
Ctrl + Page Down	Open next drawing
Ctrl + Page Up	Open previous drawing
G	Add orthogonal dimension
F	Add free dimension
Ctrl + M	Add to master drawing catalog
Shift + R	Recreate drawing
In Master Drawing Catalog:	
Ctrl + A	Select all
Alt + A	Create drawings for all parts
Alt + C	Create drawings
Alt + U	User-defined attributes
Ctrl + R	Revision

User Coordinate System (UCS)

U	Set coordinate system origin
Shift + U	Set coordinate system by two points
Ctrl + T	Toggle orientation
Ctrl + 1	Reset current
Ctrl + 0	Reset all

Source: Tekla support