



# CircuitStudio cheat sheet

## File

|           |                            |
|-----------|----------------------------|
| Ctrl + O  | Open any existing document |
| Ctrl + F4 | Close active document      |
| Alt + F4  | Exit from application      |

## Project

|                    |                                  |
|--------------------|----------------------------------|
| Ctrl + Shift + F3  | Cross probe next message         |
| Ctrl + Shift + F4  | Cross probe previous message     |
| Ctrl + Alt + O     | Select project documents to open |
| Ctrl + Tab         | Open next tab window             |
| Ctrl + Shift + Tab | Open previous tab window         |
| Alt + Left arrow   | Step back                        |
| Alt + Right arrow  | Step forward                     |
| F5                 | Refresh current page             |

## Reports

|          |                                     |
|----------|-------------------------------------|
| Ctrl + M | Measure distance between two points |
|----------|-------------------------------------|

## Window

|            |                         |
|------------|-------------------------|
| Shift + F4 | Tile all open documents |
|------------|-------------------------|

## Schematic

|                           |                                        |
|---------------------------|----------------------------------------|
| Shift + Left arrow        | Move cursor left large step            |
| Left arrow                | Move cursor left small step            |
| Ctrl + Left arrow         | Move selected object left small step   |
| Shift + Ctrl + Left arrow | Move selected object left large step   |
| Shift + Up arrow          | Move cursor up large step              |
| Up arrow                  | Move cursor up small step              |
| Ctrl + Up arrow           | Move selected objects up small step    |
| Shift + Ctrl + Up arrow   | Move selected objects up large step    |
| Shift + Right arrow       | Move cursor right large step           |
| Right arrow               | Move cursor right small step           |
| Ctrl + Right arrow        | Move selected objects right small step |

Shift + Ctrl + Right arrow Move selected objects right large step

Shift + Down arrow Move cursor down large step

Down arrow Move cursor down small step

Ctrl + Down arrow Move selected objects down small step

Shift + Ctrl + Down arrow Move selected objects down large step

## PCB

Ctrl + D Configure show/hide preferences

Shift + Page Up Zoom-in small increments

Shift + Page Down Zoom-out small increments

Ctrl + Page Up Zoom to 400%

\* Display next enabled signal layer

Shift + \* Display previous enabled signal layer

Alt + End Redraw current layer

Shift + Arrow keys Move cursor up by ten snap grid units

Arrow keys Move cursor by one snap grid unit

Alt + Left arrow Display previous component in library

Alt + Right arrow Display next component in library

## Interactive

F1 Help

Page Up Zoom in

Page Down Zoom out

End Redraw

Home Zoom pan

Arrow keys Move cursor by one grid (shift down x10)

Shift + Arrow keys Move cursor by ten grid

` Display popup menu

Backspace Remove vertex

Space Toggle wire start/end mode

*Last modification: 13/7/2023 15:24:08*

*More information:* [defkey.com/es/circuitstudio-shortcuts](https://defkey.com/es/circuitstudio-shortcuts)

[Customize this PDF...](#)