

PowerMill 2023 (Simulation) cheat sheet

Simulation tab

Note 1: To use these shortcuts, the keyboard focus has to be in the graphics window, so first click in the graphics window.

Note 2: Step sizes depends on your selection from the Simulation tab > Simulation Controls > Increment menu.

| Space | Plays the simulation to the end |
|-------------------------------|---|
| Ctrl + Space | Plays the simulation to the end of the current item |
| Right arrow | Advance one point through the simulation |
| Right arrow + Ctrl | Advance five points through the simulation |
| Right arrow + Ctrl + Shift | Advance fifty steps through the simulation |
| Right arrow + Shift | Advance one tenth of a point through the simulation |
| Left arrow | Reverse one point through the simulation |
| Left arrow + Ctrl | Reverse five points through the simulation |
| Left arrow + Ctrl + Shift | Reverse fifty steps through the simulation |
| Left arrow + Shift | Reverse one tenth of a point through the simulation |
| Shift + Page Up | Advance to the next component |
| Shift + Page Down | Reverse to the last component |
| Page Up | Advance to the next NC item or connection |
| Page Down | Reverse to the previous NC item or connection |
| End | Moves the tool to the end of the toolpath |
| Home | Moves the tool to the start of the toolpath |
| • • • • • • | |

Source: Autodesk help

Last modification: 10.06.2022 11:52:24

More information: defkey.com/kk/autodeskpowermill-2023-simulation-shortcuts

Customize this PDF...