

OrCAD PCB Editor cheat sheet

Zooms / View

F2	Zoom fit
F11	Zoom in
F12	Zoom out
Shift + F11	Zoom previous
Shift + F12	Zoom world
Ctrl + N	New
Ctrl + O	Open

General

F3	Add connect
F4	Show element
F5	Redraw
F6	Done
F7	Next
F8	Oops
F9	Cancel
F10	Grid toggle
Ctrl + F5	Color dialog box
Shift + F2	Property edit
Shift + F3	Slide
Shift + F4	Show measure
R	Rotate
Arrow keys	Pan
Shift + F5	Copy
Shift + F6	Move
Shift + F7	Dehighlight all
Shift + F8	Highlight pick
Shift + F9	Vertex
Shift + F10	Save as temp
Ctrl + D	Delete

Source: PCB Editor cheat sheet (PDF)

Last modification: 12/22/2021 8:15:01 PM

More information: defkey.com/orcad-pcb-editor-shortcuts

[Customize this PDF...](#)